



# Set-up hoist

- Mobile crane for set-up of clamping devices without a factory crane
- Designed for flexible use on different machines
- User-friendly electric hoist with integrated battery

# Set-up hoist

**Interested?**

Contact us for more details:  
Phone: +49 7144.907- 333  
or sales@hainbuch.de

## Technical data

|   |  |
|---|--|
| Max. crane payload:   | 120 kg   |
| Dimensions of the set-up hoist<br>[Swivel arm is not extended]: | L 1.8 m x W 0.8 m x H 2.05 m                               |
| Turning circle:   | 1.7 m  |
| Size of the storage surface:                                    | 1/2 Euro-pallet  |
| Battery   | Rechargeable lead-acid battery [charge life: about 1 week] |

## Set-up of machines with heavy clamping devices, without a factory crane, is this easy:



All required clamping devices can be placed on the storage surface of the set-up hoist. A surface half the size of a Euro-pallet is available for storage.

→ All clamping devices are then within easy reach during the set-up process



A permanently installed lift truck is used to position the set-up hoist with the required clamping devices next to the machine. This might be machine A today and machine B tomorrow.

→ Designed for flexible use on different machines



Positioning of the set-up hoist in front of the machine. The swivel arm is extended without the clamping device to determine the perfect position.

→ Swivel arm is more flexible than a factory crane from above – ideal for hard-to-reach spindles



After lowering the set-up hoist, integrated safety prompts ensure a stable position and give the go-ahead for the actual set-up process.

→ No additional securing of the set-up hoist is necessary



With the swivel arm, pick up the clamping device from the storage surface, position on the spindle and mount

→ Reduce set-up times